


TPMS

Coverage Application List V.58.1.0a



**BEST
COVERAGE**



TPS KEY



TPS



AXONE S TPS



COPERTURA VEICOLI TPMS VERSIONE 58.1.0a

Questa versione software dedicata ai prodotti TPMS (TPS e TPS KEY) per la manutenzione degli pneumatici arricchisce il database degli strumenti TEXA con importanti novità:

- La funzione TWS (TEXA WIRELESS SCAN) è stata ulteriormente potenziata rendendola più veloce e ancora più affidabile e precisa nell'eseguire la scansione dei diversi sensori.

- Il già ricco database dei sensori sui quali è possibile intervenire è stato ora ulteriormente esteso anche ai nuovissimi:

- **EZ-sensor 2.0** ®
- **T-PRO2** ®
- **Alcar by Schrader** ®

- La copertura dei veicoli sui quali è possibile leggere/codificare/programmare i differenti sensori è stata arricchita di nuovi modelli rendendo il database TPMS di TEXA fra i più completi disponibili ad oggi sul mercato!

Buon lavoro!

TEXA S.p.A.

TPMS VEHICLE COVERAGE VERSION 58.1.0a

This software version dedicated to the TPMS products (TPS and TPS KEY) for tyre maintenance enhances the database of TEXA's tools with important new features:

- The TWS (TEXA WIRELESS SCAN) function has been further increased making it quicker and even more reliable and precise while scanning the different sensors;

- The already rich database of the sensors on which it is possible to work on, has been extended to the very new:

- **EZ-sensor 2.0** ®
- **T-PRO2** ®
- **Alcar by Schrader** ®

- The coverage of vehicles on which it is possible to read/code/programme the different sensors has been implemented with new models, making TEXA's TPMS database among the most complete ones that are available on the market today!

Good luck with your work!

TEXA S.p.A.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR* | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|----------------------|--------------------------------|----------|--------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| ABARTH | 500 [08>] (150) | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | 500 [10>] (150) C | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Punto [07>12] (199) | - | - | - | - | T-Pro 2 | - |
| | Punto [10>] (199) Evo | - | - | - | - | T-Pro 2 | - |
| | Punto [12>] (199) | - | - | - | - | T-Pro 2 | - |
| ALFA ROMEO | 159 [05>13] | - | - | - | - | T-Pro 2 | - |
| | 159 [06>13] Station Wagon | - | - | - | - | T-Pro 2 | - |
| | 4C [13>] | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | 8C [07>09] | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 8C [08>10] Spider | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Brera [05>11] (939) | - | - | - | - | T-Pro 2 | - |
| | Giulietta [10>] (940) | [>12/13] | - | - | - | T-Pro 2 | - |
| | Giulietta [10>] (940) | [01/14>] | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Mito [08>] (955) | [>12/13] | - | - | - | T-Pro 2 | - |
| | Mito [08>] (955) | [01/14>] | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Spider [06>11] (939) | [01/15>] | RSX | - | - | T-Pro 2 | - |
| Spider [06>11] (939) | [>12/14] | - | - | - | T-Pro 2 | - | |
| ASTON MARTIN | DB9 [04>] Cabrio | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | DB9 [04>] Coupé | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | DB9 [04>12] Coupé | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | DB9 [04>12] Volante | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | DBS [07>] | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | DBS [07>12] Coupé | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| AUDI | A1 [11>] (8X1/8XF) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | A1 [12>] (8XA/8XK) Sportback | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | A3 [03>13] (8P1) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | A3 [03>13] (8PA) Sportback | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | A3 [08>14] (8P7) Cabrio | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | A3 [12>] (8V1) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | A3 [12>] (8VA) Sportback | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | A3 [14>] (8V7) Cabrio | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | A3 [14>] (8VS) Sedan | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | A4 [94>02] (8D5) Avant | [01/01>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A4 [00>05] (8E2) | [01/01>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A4 [01>05] (8E5) Avant | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A4 [02>06] (8H7) Cabrio | [11/04>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A4 [04>08] (8EC) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A4 [04>08] (8ED) Avant | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A4 [05>09] (8HE) Cabrio | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A4 [07>] (8K2) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A4 [07>] (8K5) Avant | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A4 [09>] (8KH) Avant Allroad | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | A5 [07>] (8T3) Coupé | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | A5 [09>] (8F7) Cabrio | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | A5 [09>] (8TA) Sportback | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | A6 [97>06] (4B2) | [03/04>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A6 [97>06] (4B5) Avant | [03/04>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A6 [98>05] (4B4) | [03/04>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A6 [98>05] (4B6) Avant | [03/04>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A6 [99>06] (4BH) Avant Allroad | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | A6 [04>11] (4F2) | [06/09>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A6 [04>11] (4F5) Avant | [06/09>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A6 [05>11] (4FH) Avant Allroad | - | RSX | - | UVS02C4 | T-Pro 1 | - |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|--------------------------|------------------------------|----------|-----------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| AUDI | A6 [11>] (4G2) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A6 [11>] (4G5) Avant | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A6 [13>] (4GH) Avant Allroad | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A7 [10>] (4GA) Sportback | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | A8 [94>02] (4D2) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | A8 [98>02] (4D8) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | A8 [99>02] (4D8) L | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | A8 [02>10] (4E2) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | A8 [02>10] (4E8) L | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | A8 [10>] (4H2) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A8 [11>] (4H8) L | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A8 [14>] (4HC) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | A8 [14>] (4HL) L | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Q3 [11>] (8UB) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Q5 [08>] (8RB) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Q5 [10>] (83B) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Q7 [06>15] (4LB) | [>05/14] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Q7 [06>15] (4LB) | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | R8 [07>] (423) Coupé | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | R8 [09>] (429) Spyder | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | R8 [11>] (422) GT Coupé | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | R8 [12>] (427) GT Spyder | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | RS3 [11>14] (8PA) Sportback | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | RS4 [00>02] (8D5) Avant | [01/01>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | RS4 [05>08] (8EC) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | RS4 [06>08] (8ED) Avant | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | RS4 [06>08] (8HE) Cabrio | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | RS4 [13>] (8K5) Avant | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | RS5 [10>] (8T3) Coupé | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | RS5 [13>] (8F7) Cabrio | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | RS6 [02>04] (4B4) | [03/04>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | RS6 [02>04] (4B6) Avant | [03/04>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | RS6 [08>12] (4F2) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | RS6 [08>12] (4F5) Avant | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | RS6 [13>] (4G5) Avant | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | RS7 [13>] (4GA) Sportback | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | S1 [13>] (8XF) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | S1 [13>] (8XK) Sportback | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | S3 [06>13] (8P1) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | S3 [06>13] (8PA) Sportback | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | S3 [14>] (8V1) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | S3 [14>] (8V7) Cabrio | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| S3 [14>] (8VA) Sportback | - | RSX | 1210-22X0 | UVS09X4 | - | - | |
| S3 [14>] (8VS) Sedan | - | RSX | 1210-22X0 | UVS09X4 | - | - | |
| S4 [97>05] (8D2) | [01/01>] | RSX | - | UVS02C4 | T-Pro 1 | - | |
| S4 [97>05] (8D5) Avant | [01/01>] | RSX | - | UVS02C4 | T-Pro 1 | - | |
| S4 [02>04] (8E2) | - | RSX | - | UVS02C4 | T-Pro 1 | - | |
| S4 [02>04] (8E5) Avant | - | RSX | - | UVS02C4 | T-Pro 1 | - | |
| S4 [04>06] (8H7) Cabrio | - | RSX | - | UVS02C4 | T-Pro 1 | - | |
| S4 [04>08] (8EC) | - | RSX | - | UVS02C4 | T-Pro 1 | - | |
| S4 [04>08] (8ED) Avant | - | RSX | - | UVS02C4 | T-Pro 1 | - | |
| S4 [06>09] (8HE) Cabrio | - | RSX | - | UVS02C4 | T-Pro 1 | - | |
| S4 [08>] (8K2) | - | RSX | - | UVS02C4 | T-Pro 1 | - | |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

This document is strictly confidential. All copying, in part or in whole, is strictly forbidden without the prior authorisation of TEXA S.p.A. Future specifications, descriptions and appearances may vary with respect to this brochure. TEXA S.p.A. reserves the right to modify its products without prior notice.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR* | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|---------------------------|---------------------------------------|----------|-----------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| AUDI | S4 [08>] (8K5) Avant | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | S5 [07>] (8T3) Coupé | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | S5 [09>] (8F7) Cabrio | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | S5 [09>] (8TA) Sportback | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | S6 [99>04] (4B4) | [03/04>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | S6 [99>05] (4B6) Avant | [03/04>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | S6 [06>11] (4F2) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | S6 [06>11] (4F5) Avant | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | S6 [12>] (4G2) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | S6 [12>] (4G5) Avant | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | S7 [10>] (4GA) Sportback | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | S8 [98>02] (4D2) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | S8 [06>10] (4E2) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | S8 [12>] (4H2) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | S8 [14>] (4HC) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | SQ5 [13>] (8RB) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| TT [14>] (FV3) Coupé | - | RSX | 1210-22X0 | UVS09X4 | - | - | |
| BENTLEY | Continental [03>11] GT | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Continental [05>11] Flying Spur | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Continental [06>11] GTC | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Continental [08>11] GT Speed | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Continental [08>11] GTC Speed | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Continental [09>11] Supersport | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Continental [10>11] Flying Spur Speed | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Continental [10>11] Supersport Cabrio | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Continental [11>] GT | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Continental [11>] GT Speed | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Continental [12>] GTC | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Continental [12>] GTC Speed | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Continental [13>] GT V8 | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Continental [13>] GT V8 Cabrio | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| Continental [14>] GT V8 S | - | RSX | - | UVS02C4 | T-Pro 1 | - | |
| Mulsanne [11>] | - | RSX | - | UVS02C4 | T-Pro 1 | - | |
| BMW | 1 [04>11] (E87) | [09/09>] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | 1 [07>11] (E81) | [09/09>] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | 1 [07>12] (E82) Coupé | [09/09>] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | 1 [08>12] (E88) Cabrio | [09/09>] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | 1 [11>] (F20) | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | 1 [12>] (F21) | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | 2 [14>] (F22) | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | 2 [14>] (F23) Cabrio | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | 2 [14>] (F45) Active Tourer | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | 3 [90>99] (E36) | [05/97>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 3 [90>99] (E36) Coupé | [05/97>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 3 [93>01] (E36) Compact | [05/97>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 3 [93>99] (E36) Cabrio | [05/97>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 3 [94>00] (E36) Touring | [05/97>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 3 [98>05] (E46) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 3 [98>05] (E46) Touring | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 3 [98>06] (E46) Coupé | [>12/04] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 3 [99>07] (E46) Cabrio | [>12/04] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 3 [01>04] (E46) Compact | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| 3 [05>11] (E90) | [09/09>] | RSX | - | UVS09X4 | T-Pro 1 | - | |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|----------------------------|----------------------------|---------------|----------------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| BMW | 3 [05>11] (E90) | [06/06>09/09] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 3 [05>12] (E91) Touring | [09/09>] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | 3 [05>12] (E91) Touring | [06/06>09/09] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 3 [06>13] (E92) Coupé | [>09/09] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 3 [06>13] (E92) Coupé | [09/09>] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | 3 [07>13] (E93) Cabrio | [09/09>] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | 3 [07>13] (E93) Cabrio | [>09/09] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 3 [12>] (F30) | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | 3 [12>] (F31) Touring | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | 3 [12>] (F35) Long | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | 3 [13>] (F34) Gran Turismo | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | 3 [14>] (F80) M | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | 4 [14>] (F32) Coupé | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | 4 [14>] (F33) Cabrio | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | 4 [14>] (F36) Gran Coupé | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | 4 [14>] (F82) M Coupé | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | 4 [14>] (F83) M Cabrio | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | 5 [95>04] (E39) | [09/98>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 5 [95>04] (E39) Touring | [09/98>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 5 [03>10] (E60) | [03/06>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 5 [04>10] (E61) Touring | [03/06>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 5 [09>] (F07) Gran Turismo | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | 5 [10>] (F10) | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | 5 [10>] (F10) | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | 5 [10>] (F11) Touring | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | 5 [10>] (F11) Touring | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | 5 [10>] (F18) Long | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | 5 [10>] (F18) Long | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | 6 [04>10] (E63) Coupé | [03/06>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 6 [04>10] (E64) Cabrio | [03/06>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 6 [11>] (F06) Gran Coupé | [>04/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | 6 [11>] (F06) Gran Coupé | [05/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | 6 [11>] (F12) Cabrio | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | 6 [11>] (F12) Cabrio | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | 6 [11>] (F13) Coupé | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | 6 [11>] (F13) Coupé | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | 7 [92>02] (E38) | [09/98>10/01] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 7 [00>08] (E65) | [03/06>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 7 [00>08] (E65) | [11/01>11/03] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 7 [00>08] (E66) | [03/06>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| 7 [00>08] (E66) | [11/01>11/03] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 | |
| 7 [02>08] (E67) Protection | [>11/03] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 | |
| 7 [02>08] (E67) Protection | [03/06>] | RSX | - | UVS02C4 | T-Pro 1 | - | |
| 7 [05>07] (E68) | [03/06>] | RSX | - | UVS02C4 | T-Pro 1 | - | |
| 7 [08>] (F01) | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - | |
| 7 [08>] (F02) | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - | |
| 7 [09>] (F03) Protection | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - | |
| 7 [10>] (F04) Hybrid | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - | |
| i3 [13>] (I01) | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 | |
| i8 [14>] (I12) | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 | |
| X1 [09>15] (E84) | [>05/14] | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 | |
| X1 [09>15] (E84) | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - | |
| X3 [04>10] (E83) | - | RSX | - | UVS02C4 | T-Pro 1 | - | |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR* | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|--------------------------|--|---------------|----------------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| BMW | X3 [10>] (F25) | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | X3 [10>] (F25) | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | X4 [14>] (F26) | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | X4 [14>] (F26) | [>05/14] | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | X5 [99>06] (E53) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | X5 [06>13] (E70) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | X5 [13>] (F15) | [>05/14] | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | X6 [08>14] (E71) | [>10/11] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | X6 [08>14] (E71) | [11/11>] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | X6 [14>] (F16) | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | X6 [14>] (F16) | [06/14>] | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | Z4 [02>09] (E85) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Z4 [06>09] (E86) Coupé | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Z4 [09>] (E89) | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Z4 [09>] (E89) | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Z4 M [06>09] (E85) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| Z4 M [06>09] (E86) Coupé | - | RSX | - | UVS02C4 | T-Pro 1 | - | |
| CADILLAC | BLS [05>] | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | BLS [07>] Station Wagon | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | CTS [03>] | [08/09>08/13] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | CTS [03>] | [07/07>07/09] | RSX | - | - | T-Pro 1 | - |
| | CTS [03>] | [09/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | DTS [05>] | - | - | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Escalade [06>] (GMT 900) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | SRX [03>] | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | STS [05>] | - | - | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | STS-V [05>] | - | - | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | XLR [03>] | - | - | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| XLR-V [05>] | - | - | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 | |
| CHEVROLET | Aveo [04>08] (T200) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Aveo [08>11] (T250) Hatchback | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Aveo [11>] (T300) Hatchback | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Aveo [11>] (T300) Sedan | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Camaro Cabrio [10>] | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Camaro Coupé [10>] | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Captiva [06>11] (C100) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Captiva [11>] (C140) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Cobalt [11>] | [02/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Corvette Stingray [14>] (C7) Convertible | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Corvette Stingray [14>] (C7) Coupé | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Cruze [09>] (J300) Hatchback | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Cruze [09>] (J300) Sedan | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Cruze [09>] (J300) Wagon | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Malibu [12>] | [07/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Malibu [12>] | [>06/14] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Orlando [11>] (J309) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Spark [09>] (M300) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Trax [13>] | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Volt [11>] | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| CHRYSLER | 300 [11>] (LX) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | 300 C [05>10] (LE) | [03/07>] | - | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | 300 C [05>10] (LE) Wagon | [03/07>] | - | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Crossfire [02>08] (ZH) | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|------------------------|---------------------------------|----------|----------------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| CHRYSLER | Grand Voyager III [07>] (RT) | [01/11>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Grand Voyager III [07>] (RT) | [>01/11] | - | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Sebring [07>10] (JS) | - | - | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Sebring [07>10] (JS) Cabrio | - | - | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Town and Country [08>10] (RT) | - | - | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Town and Country [11>] (RT) | [>06/14] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Town and Country [11>] (RT) | [07/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| CITROEN | #Jumpy 3 (G9) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Berlingo (B9) Van | [>09/13] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Berlingo (B9) Van | [10/13>] | - | 1210-22X0 | - | T-Pro 2 | - |
| | Berlingo (M59) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Berlingo [02>08] (M59) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Berlingo [08>] (B9) | [>09/13] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Berlingo [08>] (B9) | [10/13>] | - | 1210-22X0 | - | T-Pro 2 | - |
| | C 3 [09>] (A51) | [>06/14] | - | - | - | - | - |
| | C 3 [09>] (A51) | [07/14>] | - | 1210-22X0 | - | T-Pro 2 | - |
| | C 3 [09>] (A58) Picasso | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | C 3 [09>] (A58) Picasso | - | - | 1210-22X0 | - | T-Pro 2 | - |
| | C 3 [10>] (A51) Van | - | - | 1210-22X0 | - | T-Pro 2 | - |
| | C 3 [12>] (Ai51) | [07/14>] | - | 1210-22X0 | - | T-Pro 2 | - |
| | C 3 [12>] (Ai51) | [>06/14] | - | - | - | - | - |
| | C 3 [12>] (Ai58) Picasso | - | - | 1210-22X0 | - | T-Pro 2 | - |
| | C 4 [04>10] (B5) | [08/08>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | C 4 [04>10] (B5) | [>06/08] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | C 4 [04>10] (B5) Coupé | [>06/08] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | C 4 [04>10] (B5) Coupé | [08/08>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | C 4 [07>10] (B5) Van | [08/08>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | C 4 [07>10] (B5) Van | [>06/08] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | C 4 [10>] (B7) | [>01/14] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | C 4 [10>] (B7) | [06/14>] | - | 1210-22X0 | - | T-Pro 2 | - |
| | C 4 [13>] L (B7) | - | - | 1210-22X0 | - | T-Pro 2 | - |
| | C 4 Aircross [12>] | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | C 4 Grand Picasso [06>13] (B58) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | C 4 Grand Picasso [13>] (B78) | [06/14>] | - | 1210-22X0 | - | T-Pro 2 | - |
| | C 4 Picasso [06>13] (B58) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | C 4 Picasso [13>] (B78) | [06/14>] | - | 1210-22X0 | - | T-Pro 2 | - |
| | C 5 [00>04] (X4) | - | - | 1210-22X0-2020 | - | - | S3AX01 |
| | C 5 [00>04] (X4) Break | - | - | 1210-22X0-2020 | - | - | S3AX01 |
| | C 5 [04>08] (X4) Facelift | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | C 5 [04>08] (X4) Facelift Break | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | C 5 [08>] (X7) | [>09/13] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | C 5 [08>] (X7) | [09/13>] | - | 1210-22X0 | - | T-Pro 2 | - |
| | C 5 [08>] (X7) Break | [>09/13] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | C 5 [08>] (X7) Break | [09/13>] | - | 1210-22X0 | - | T-Pro 2 | - |
| | C 6 [06>10] (X6) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | C 8 [02>] | [09/05>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | C 8 [02>] | [>10/05] | - | 1210-22X0-2020 | - | - | S3AX01 |
| C-Elysée [12>] | - | - | 1210-22X0 | - | T-Pro 2 | - | |
| DS3 [10>] (A55) | - | - | 1210-22X0 | - | T-Pro 2 | - | |
| DS3 [13>] (A55) Cabrio | - | - | 1210-22X0 | - | T-Pro 2 | - | |
| DS4 [11>] (B75) | [>01/14] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 | |
| DS4 [11>] (B75) | [02/14>] | - | 1210-22X0 | - | T-Pro 2 | - | |
| DS5 [11>] (B81) | [>01/14] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 | |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR* | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|----------------------------|-----------------------------------|----------|----------------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| CITROEN | DS5 [11>] (B81) | [02/14>] | - | 1210-22X0 | - | T-Pro 2 | - |
| | Jumper (U5) | [>11/13] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Jumper (U5) | [01/14>] | - | 1210-22X0 | - | T-Pro 2 | - |
| | Jumper (U9) | [>11/13] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Jumper (U9) | [01/14>] | - | 1210-22X0 | - | T-Pro 2 | - |
| | Jumpy 3 [07>] (G9) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Nemo | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Nemo Multispace [08>] | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| DACIA | #Dokker [12>] | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Dokker [12>] (FE) | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Duster [10>13] (HS) | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Duster [13>] (HS) | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Lodgy [12>] (JS) | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Logan [12>] (L8) | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Sandero [13>] (B8) | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| DAEWOO | Genra [08>] | [08/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Nexia II [08>] | [06/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| DODGE | # RAM 2500 [11>] (DJ) | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | # RAM 3500 [11>] (D2) Pick-Up | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | # RAM 3500 [11>] (DD) Cab Chassis | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | # RAM 4500/5500 [11>] (DP) | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Avenger [07>10] (JS) | - | - | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Avenger [11>] (JS) | - | - | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Caliber [06>12] (PM) | - | - | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Challenger [08>] (LC) | [02/10>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Challenger [08>] (LC) | [>01/10] | - | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Charger [06>09] (LX) | - | - | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Charger [11>] (LD) | [>09/14] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Charger [11>] (LD) | [10/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Durango [11>] (WD) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Grand Caravan [11>] (RT) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Journey [10>] (JC) | [07/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Journey [10>] (JC) | [>06/14] | - | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Nitro [07>12] (KA) | - | - | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | RAM 1500 [11>] (DS) | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | RAM 2500 [11>] (DJ) | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | RAM 3500 [11>] (D2) Pick-Up | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | RAM 3500 [11>] (DD) Cab Chassis | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | RAM 4000 [11>] (DX) Cab Chassis | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | RAM 4500/5500 [11>] (DP) | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| Viper [12>] (VX) SRT Coupé | [07/15>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 | |
| FERRARI | 575M [03>07] (F133) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 599 GTB Fiorano [06>12] (F141) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 612 Scaglietti [04>07] (F137) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 612 Scaglietti [07>11] (F137 MY) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | California [09>] (F149) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | F430 [05>09] (F131) | [>06/07] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | F430 [05>09] (F131) | [07/07>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | F430 [05>09] (F131) Spider | [>06/07] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | F430 [05>09] (F131) Spider | [07/07>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | F430 [07>09] (F131) Challenge | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | F458 [09>14] (F142) Italia | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | F458 [10>14] (F142) Challenge | - | RSX | - | UVS02C4 | T-Pro 1 | - |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.
*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0
Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.
*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

This document is strictly confidential. All copying, in part or in whole, is strictly forbidden without the prior authorisation of TEXA S.p.A. Future specifications, descriptions and appearances may vary with respect to this brochure. TEXA S.p.A. reserves the right to modify its products without prior notice.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|--------------------------|---|---------------|----------------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| FERRARI | F458 [11>14] (F142) Spider | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | F550 [96>02] (F133) Maranello | [03/02>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | F550 [00>01] (F133) Maranello Barchetta | [03/02>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | FF [11>] (F140) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| FIAT | 500 [07>] (150) | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | 500 [09>] (150) C | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | 500L [12>] (330) | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | 500L [13>] (334) Living | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Albea [02>] | [10/13>] | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Bravo [07>13] (198) | - | - | - | - | T-Pro 2 | - |
| | Bravo [08>13] (198) Van | - | - | - | - | T-Pro 2 | - |
| | Bravo [14>] (198) Facelift | [>09/14] | - | - | - | T-Pro 2 | - |
| | Doblò [10>15] (152) | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Doblò Cargo (263) [10>15] | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Ducato (X250) [06>] Minibus | [01/06>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Ducato (X250) FL [11>14] | [01/06>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Ducato (X250) FL [14>] | [01/06>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Fiorino | [10/07>] | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Fiorino 08 (225) | [10/07>] | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Fiorino Pick-Up | [10/07>] | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Freemont [11>] | [03/11>06/14] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Freemont [11>] | [07/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Idea [03>12] (135) | - | - | - | - | - | - |
| | Idea [03>12] (135) Van | - | - | - | - | - | - |
| | Linea [07>] | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Palio III [09>] Facelift | [08/11>] | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Palio IV [11>] | [08/11>] | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Panda [12>] (319) | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Punto [05>12] (199) | - | - | - | - | T-Pro 2 | - |
| | Punto [06>12] (199) Van | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Punto [09>] (199) Evo | - | - | - | - | T-Pro 2 | - |
| | Punto [09>] (199) Evo Van | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Punto [12>] (199) | - | - | - | - | T-Pro 2 | - |
| | Qubo [08>] (300) | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Scudo (222) Facelift | [09/06>] | - | 1210-22X0 | - | - | - |
| | Scudo (272) | - | - | 1210-22X0 | - | - | - |
| | Sedici [06>] (189) | [06/14>] | - | - | - | T-Pro 2 | - |
| | Strada [98>05] (278) | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Strada I [00>04] Facelift | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Strada II [05>09] (278) Facelift | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Strada III [08>] Novo | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Strada III [08>] Novo Adventure | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Strada III [10>] Facelift | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Ulysse [02>11] (179) | [>10/05] | - | 1210-22X0-2020 | - | - | S3AX01 |
| Ulysse [06>11] (179) Van | [>10/10] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 | |
| FORD | B-Max [12>] | [06/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | C-Max [10>15] | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | EcoSport [13>] | [10/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | EcoSport [13>] | [>09/14] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Fiesta [08>13] | [06/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Fiesta [09>13] Van | [06/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Fiesta [13>] Facelift | [06/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Focus [11>14] | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR* | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|---------------------------|--|----------|----------------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| FORD | Focus [11>14] Turnier | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Galaxy [06>] (WA6) | - | RSX | - | UVS401X | T-Pro 2 | - |
| | Ka [08>15] (RU8) | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Kuga [08>12] | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Kuga [13>] (DM2) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Mondeo IV [06>14] (BA7) | [10/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Mondeo IV [06>14] (BA7) | [>10/14] | RSX | - | UVS401X | T-Pro 2 | - |
| | Mondeo IV [06>14] (BA7) Turnier | [>10/14] | RSX | - | UVS401X | T-Pro 2 | - |
| | Mondeo IV [06>14] (BA7) Turnier | [10/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Mustang V [04>09] (S197) Cabrio | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Mustang V [04>09] (S197) Coupé | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Mustang V [10>] (S197) Facelift Cabrio | [>04/14] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Mustang V [10>] (S197) Facelift Cabrio | [05/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Mustang V [10>] (S197) Facelift Coupé | [>04/14] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Mustang V [10>] (S197) Facelift Coupé | [05/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Ranger [06>11] | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Ranger [12>] | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | S-Max [06>15] | - | RSX | - | UVS401X | T-Pro 2 | - |
| HONDA | Accord [08>] (CU) Sedan | [03/14>] | - | - | - | T-Pro 2 | - |
| | Accord [08>] (CU) Tourer | [03/14>] | - | - | - | T-Pro 2 | - |
| | Civic [12>] (FB/FG) Hatchback | [06/14>] | - | - | - | - | - |
| | Civic [12>] (FB/FG) Hatchback Hybrid | [06/14>] | - | - | - | - | - |
| | Jazz [08>14] (GE) | - | - | - | - | T-Pro 2 | - |
| HUMMER | H2 [03>] | [>12/08] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | H3 [05>] | [>01/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| HYUNDAI | Accent Solaris [11>] (RB) | [03/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 2 | S3AX01 |
| | Accent V [11>] (RB) | [03/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 2 | S3AX01 |
| | Elantra [11>] (MD) | [03/14>] | RSX | - | - | - | - |
| | Elantra [13>] (JK) Coupé | [03/14>] | RSX | - | - | - | - |
| | Equus [14>] (VI) Limousine | - | RSX | - | - | T-Pro 2 | - |
| | Equus [14>] (VI) Sedan | - | RSX | - | - | T-Pro 2 | - |
| | Genesis [09>13] (BH) | [01/14>] | RSX | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Genesis [09>13] (BK) Coupé | [03/14>] | RSX | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Grandeur [11>] (HG) | [03/14>] | RSX | - | - | T-Pro 2 | - |
| | i10 [07>13] (PA) | - | RSX | - | - | T-Pro 2 | - |
| | i10 [07>13] Grand (BA) | - | RSX | - | - | T-Pro 2 | - |
| | i10 [13>] (IA) | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | i20 [08>14] (PB) | [>06/14] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 2 | S3AX01 |
| | i20 [08>14] (PB) | [11/14>] | - | 1210-22X0 | - | - | - |
| | i30 [08>12] (FD) | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 2 | S3AX01 |
| | i30 [08>12] (FD) Kombi | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 2 | S3AX01 |
| | i30 [12>] (GD) | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | i30 [12>] (GD) Kombi | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | i40 [11>] (VF) | [04/14>] | RSX | - | - | T-Pro 2 | - |
| | i40 [11>] (VF) | [>03/14] | RSX | - | - | T-Pro 2 | - |
| | i40 [12>] (VF) Sedan | [>03/14] | RSX | - | - | T-Pro 2 | - |
| | i40 [12>] (VF) Sedan | [04/14>] | RSX | - | - | T-Pro 2 | - |
| | ix20 [10>] (JC) | [>09/13] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 2 | S3AX01 |
| ix20 [10>] (JC) | [05/13>] | RSX | 1210-22X0 | UVS401X | T-Pro 2 | - | |
| ix35/Tucson [09>] (EL/LM) | [>09/15] | RSX | 1210-22X0-2020 | - | - | S3AX01 | |
| ix35/Tucson [09>] (EL/LM) | [09/15>] | - | 1210-22X0 | - | - | - | |
| ix55 [07>] (EN) | [03/14>] | RSX | - | - | - | - | |
| Santa Fe [06>12] (CM) | - | RSX | 1210-22X0 | - | - | S3AX01 | |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|-----------------------------|-------------------------------------|---------------|-----------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| HYUNDAI | Santa Fe [12>] (DM) | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Sonata VI [09>14] (YF) | [03/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 2 | S3AX01 |
| | Sonata VI [11>14] (YF) Hybrid | [03/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 2 | S3AX01 |
| | Tucson [04>] (JM) | [08/06>] | RSX | - | - | - | - |
| | Veloster [11>] Coupé | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Veracruz [07>] (EN) | [>02/11] | RSX | - | - | - | - |
| INFINITI | EX [07>13] (J50) | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | FX [08>13] (S51) | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | G [06>12] (V36) Sedan | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | G [08>12] (V36) Coupé | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | G [09>12] (V36) Cabrio | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | M [10>13] (Y51) | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| JAGUAR | XF [08>15] (X250) | - | RSX | - | - | - | - |
| | XF [09>15] (X250) R | - | RSX | - | - | - | - |
| | XJ [03>10] (X350/X358) | [10/05>] | RSX | - | - | - | - |
| | XJ [10>] (X351) | - | RSX | - | - | - | - |
| | XK [06>14] (X150) Cabrio | - | RSX | - | - | - | - |
| | XK [06>14] (X150) Coupé | - | RSX | - | - | - | - |
| | XK [06>14] (X150) R Cabrio | - | RSX | - | - | - | - |
| | XK [06>14] (X150) R Coupé | - | RSX | - | - | - | - |
| | X-Type [01>09] (X400) | [01/07>] | RSX | - | - | - | - |
| X-Type [03>09] (X400) Wagon | [01/07>] | RSX | - | - | - | - | |
| JEEP | Cherokee [08>13] (KK) | - | - | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Commander [06>10] (XH/XK) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Compass [06>11] (MK) | - | - | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Compass [11>] (MK) Facelift | - | - | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Grand Cherokee [05>10] (WH) | - | - | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Grand Cherokee [05>10] (WK) | - | - | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Grand Cherokee [11>13] (WK2) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Grand Cherokee [13>] (WK2) Facelift | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Patriot [06>] (MK) | - | - | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Wrangler [07>] (JK) | [>09/10] | - | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Wrangler [07>] (JK) | [12/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Wrangler [07>] (JK) | [09/10>12/13] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| KIA | Cadenza [10>] (VG) | [10/13>] | RSX | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Carens IV [13>] (RP) | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Cee'd [06>12] (ED) | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 2 | S3AX01 |
| | Cee'd [07>12] (ED) Sporty Wagon | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 2 | S3AX01 |
| | Cee'd [12>] (JD) | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Cee'd [12>] (JD) Sporty Wagon | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Cerato [13>] (YD) | - | - | - | - | - | - |
| | Optima III [11>] (TF) | [>08/13] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 2 | S3AX01 |
| | Optima III [11>] (TF) | [08/13>] | RSX | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Optima III [12>] (TF) Hybrid | [>08/13] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 2 | S3AX01 |
| | Optima III [12>] (TF) Hybrid | [08/13>] | RSX | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Picanto [11>] (TA) | [06/14>] | RSX | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Quoris [13>] (KH) | - | RSX | - | - | T-Pro 2 | - |
| | Rio [00>05] (BC/DC) | - | RSX | - | - | - | - |
| | Rio [02>05] (BC/DC) Kombi | - | RSX | - | - | - | - |
| | Rio [05>11] (JB) | - | RSX | - | - | - | - |
| | Rio [11>] (UB) | - | RSX | - | - | - | - |
| | Sorento II [09>14] (XM) | [>09/12] | RSX | - | - | - | - |
| Sorento II [09>14] (XM) | [07/12>] | RSX | 1210-22X0 | UVS401X | T-Pro 2 | - | |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR* | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|--------------------------------------|--|----------|----------------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| KIA | Soul [09>13] (AM) | [11/13>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Soul [09>13] (AM) | [>10/13] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 2 | S3AX01 |
| | Sportage [10>] (SL) | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Venga [10>] (YN) | [>02/14] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 2 | S3AX01 |
| | Venga [10>] (YN) | [03/14>] | RSX | 1210-22X0 | UVS401X | T-Pro 2 | - |
| LAMBORGHINI | Aventador [11>] LP 700-4 | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Aventador [12>] LP 700-4 Roadster | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Gallardo [03>08] | [01/07>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Gallardo [06>08] Spyder | [01/07>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Gallardo [07>08] Superleggera | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Gallardo [09>14] LP 560-4 | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Gallardo [09>14] LP 560-4 Spyder | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Gallardo [10>14] LP 550-2 | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Gallardo [10>14] LP 570-4 Superleggera | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Gallardo [11>14] LP 550-2 Spyder | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Gallardo [11>14] LP 570-4 Spyder Performante | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Murcièlago [02>06] | [01/06>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Murcièlago [04>06] Roadster | [01/06>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Murcièlago [06>10] LP 640-4 | [01/06>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Murcièlago [06>10] LP 640-4 Roadster | [01/06>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| Murcièlago [09>10] LP 650-4 Roadster | [01/06>] | RSX | - | UVS02C4 | T-Pro 1 | - | |
| Murcièlago [09>10] LP 670-4 SV | [01/06>] | RSX | - | UVS02C4 | T-Pro 1 | - | |
| LANCIA | Delta [08>13] (181) | - | - | - | - | T-Pro 2 | - |
| | Delta [08>13] (181) | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Delta [14>] (181) Facelift | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Flavia [12>] | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 2 | S3AX01 |
| | Musa [04>] | - | - | - | - | - | - |
| | Thema [11>] | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Voyager [11>] | [08/13>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Voyager [11>] | [>07/13] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Ypsilon [11>] | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| LAND ROVER | Discovery III [04>09] (TA) | - | RSX | - | - | T-Pro 2 | - |
| | Discovery IV [09>] (LA) | - | RSX | - | - | T-Pro 2 | - |
| | Freelander II [07>13] (LF) | [>07/14] | RSX | - | - | - | - |
| | Freelander II [07>13] (LF) | [07/14>] | RSX | - | - | T-Pro 2 | - |
| | Range Rover Evoque [11>] (LV) | [07/14>] | RSX | - | - | T-Pro 2 | - |
| | Range Rover III [02>09] (LM) | [>02/03] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Range Rover III [02>09] (LM) | [01/05>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Range Rover III [06>12] (LM) Facelift | [>08/09] | RSX | - | - | T-Pro 2 | - |
| | Range Rover Sport I [05>09] (LS) | - | RSX | - | - | T-Pro 2 | - |
| | Range Rover Sport I [09>13] (LS) Facelift | - | RSX | - | - | T-Pro 2 | - |
| | Range Rover Sport II [14>] (LW) | - | RSX | - | - | T-Pro 2 | - |
| LEXUS | CT (A1) 200h [11>] | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | ES (V4) 240 [09>12] | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | ES (V6) 250 [12>] | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | ES (V6) 300h [12>] | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | ES (V6) 350 [12>] | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | GS (S1) 300 [05>10] | - | RSX | - | - | T-Pro 1 | - |
| | GS (S1) 350 [05>11] | - | RSX | - | - | T-Pro 1 | - |
| | GS (S1) 450h [06>11] | - | RSX | - | - | T-Pro 1 | - |
| | GS (S1) 460 [07>11] | - | RSX | - | - | T-Pro 1 | - |
| GS (L1) 250 [12>] | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 | |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.
*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0
Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.
*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

This document is strictly confidential. All copying, in part or in whole, is strictly forbidden without the prior authorisation of TEXA S.p.A. Future specifications, descriptions and appearances may vary with respect to this brochure. TEXA S.p.A. reserves the right to modify its products without prior notice.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|---------------|--------------------------------------|---------------|--------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| LEXUS | GS (L1) 350 [12>] | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | GS (L1) 450h [12>] | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | GX (J15) 400 [13>] | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | GX (J15) 460 [09>] | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | IS (E3) 250 [13>] Sedan | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | IS (E3) 300h [13>] Sedan | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | IS (E3) 350 [13>] Sedan | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | LFA (A1) [10>12] | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | LS (F4) 460 [07>] | [>12/13] | RSX | - | - | T-Pro 1 | - |
| | LS (F4) 460 [07>] | [01/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | LS (F4) 600h [07>] | [01/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | LS (F4) 600h [07>] | [>12/13] | RSX | - | - | T-Pro 1 | - |
| | LX (J2) 570 [07>] | [>05/14] | RSX | - | - | T-Pro 1 | - |
| | LX (J2) 570 [07>] | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | RX (L1) 270 [10>] | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | RX (L1) 350 [10>] | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | RX (L1) 450h [09>] | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | SC (Z4) 430 [01>10] | [06/06>] | RSX | - | - | T-Pro 1 | - |
| LOTUS | Elise [00>] | [01/08>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Exige [00>] | [01/08>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| MARUTI | SX4 [07>] | [06/14>] | - | - | - | T-Pro 2 | - |
| MASERATI | Coupé [01>07] (M138) | [04/04>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Ghibli [13>] (M157) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | GranTurismo [07>] (M145) | [01/11>12/13] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | GranTurismo [07>] (M145) | [01/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | GranTurismo [07>] (M145) | [>01/11] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | GranTurismo [10>] Convertible (M145) | [01/11>12/13] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | GranTurismo [10>] Convertible (M145) | [01/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | GranTurismo [10>] Convertible (M145) | [>01/11] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Quattroporte V [04>07] (M139) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Quattroporte V [07>12] (M139 EV07) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Quattroporte VI [13>] (M156) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| MAYBACH | Maybach 57 [02>] | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Maybach 62 [02>] | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| MAZDA | BT-50 [06>11] (UN) | [05/11>] | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | CX-5 [12>] (KE) | - | RSX | - | - | T-Pro 2 | - |
| | CX-7 [07>12] (ER) | [06/09>] | RSX | - | - | T-Pro 2 | - |
| | CX-9 [07>] (TB) | [08/10>] | RSX | - | - | T-Pro 2 | - |
| | Mazda2 [07>14] (DE) | - | RSX | - | - | T-Pro 2 | - |
| | Mazda3 [09>13] (BL) | - | RSX | - | - | T-Pro 2 | - |
| | Mazda3 [14>] (BM) | - | RSX | - | - | T-Pro 2 | - |
| | Mazda5 [10>15] (CW) | - | RSX | - | - | T-Pro 2 | - |
| | Mazda6 [07>13] (GH) | - | RSX | - | - | T-Pro 2 | - |
| | Mazda6 [07>13] (GH) Sport Tourer | - | RSX | - | - | T-Pro 2 | - |
| | Mazda6 [07>13] (GH) Station Wagon | - | RSX | - | - | T-Pro 2 | - |
| | Mazda6 [14>] (GJ) | - | RSX | - | - | T-Pro 2 | - |
| | Mazda6 [14>] (GJ) Station Wagon | - | RSX | - | - | T-Pro 2 | - |
| | MX-5 [05>15] (NC) | - | RSX | - | - | T-Pro 2 | - |
| MERCEDES-BENZ | #Sprinter 2500 (906) | [01/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | #Sprinter 2500 (906) | [>10/11] | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | #Sprinter 3500 (906) | [01/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | #Sprinter 3500 (906) | [>10/11] | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | A [12>] (176) | [01/13>03/14] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR* | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|----------------------|--------------------------------|----------|----------------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| MERCEDES-BENZ | A [12>] (176) | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | A [12>] (176) | [04/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | B [11>] (246) | [01/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | B [11>] (246) | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | C [07>14] (204) | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | C [07>14] (204) | [01/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | C [07>14] (204) T | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | C [07>14] (204) T | [01/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | C [11>14] (204) Coupé | [01/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | C [11>14] (204) Coupé | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | C [14>] (205) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | C [14>] (205) L | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | C [14>] (205) T | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Citan | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Citan [13>] (415) | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | CL [99>06] (215) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | CL [06>] (216) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | CLA [13>] (117) | [>06/14] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | CLA [13>] (117) | [06/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | CLK [96>02] (208) Coupé | [01/02>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | CLK [96>03] (208) Cabrio | [01/02>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | CLK [02>09] (209) Coupé | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | CLK [02>10] (209) Cabrio | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | CLS [04>10] (219) Coupé | [01/05>] | RSX | - | - | T-Pro 2 | - |
| | CLS [04>10] (219) Coupé | [>01/05] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | CLS [11>] (218) Coupé | [01/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | CLS [11>] (218) Coupé | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | CLS [11>] (218) Shooting Brake | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | CLS [11>] (218) Shooting Brake | [01/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | E [95>03] (210) | [11/01>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | E [95>03] (210) T | [11/01>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | E [96>03] (210) T L | [11/01>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | E [02>09] (211) | [>01/05] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | E [02>09] (211) T | [>01/05] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | E [03>09] (211) T L | [>01/05] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | E [09>] (207) Coupé | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | E [09>] (207) Coupé | [12/12>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | E [09>] (212) | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | E [09>] (212) | [01/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | E [09>] (212) T | [01/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| E [09>] (212) T | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 | |
| E [10>] (207) Cabrio | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 | |
| E [10>] (207) Cabrio | [01/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 | |
| E [11>] (212) L | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 | |
| E [11>] (212) L | [01/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 | |
| G [92>] (461) | [01/97>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 | |
| G [92>] (461) | [12/12>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 | |
| G [93>] (463) | [01/97>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 | |
| G [93>] (463) | [12/12>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 | |
| G [93>] (463) T | [01/97>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 | |
| G [93>] (463) T | [12/12>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 | |
| G [96>] (463) Cabrio | [01/97>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 | |
| G [96>] (463) Cabrio | [12/12>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 | |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|-------------------------|-----------------------------------|---------------|----------------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| MERCEDES-BENZ | G [98>] (463) T L | [01/97>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | G [98>] (463) T L | [12/12>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | GL [06>12] (164) | [>06/09] | RSX | - | - | T-Pro 2 | - |
| | GL [06>12] (164) | [06/09>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | GL/GLS [12>] (166) | [01/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | GLA [13>] (156) | [01/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | GLK [08>] (204) | [12/12>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | GLK [08>] (204) | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | ML [05>11] (164) | - | RSX | - | - | T-Pro 2 | - |
| | ML/GLE [11>] (166) | [12/12>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | ML/GLE [11>] (166) | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | R [06>13] (251) | [>06/09] | RSX | - | - | T-Pro 2 | - |
| | R [06>13] (251) | [06/09>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | R [06>13] (251) | [12/12>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | R [06>13] (251) L | [>06/09] | RSX | - | - | T-Pro 2 | - |
| | R [06>13] (251) L | [06/09>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | R [06>13] (251) L | [12/12>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | S [98>06] (220) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | S [98>06] (220) L | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | S [99>06] (220) LL | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | S [05>13] (221) | [>06/09] | RSX | - | - | T-Pro 2 | - |
| | S [05>13] (221) | [07/09>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | S [05>13] (221) L | [07/09>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | S [05>13] (221) L | [>06/09] | RSX | - | - | T-Pro 2 | - |
| | S [13>] (222) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | S [13>] (222) L | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | S [14>] (217) Coupé | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | SL [01>12] (230) | [02/05>07/09] | RSX | - | - | T-Pro 2 | - |
| | SL [01>12] (230) | [>01/05] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | SL [01>12] (230) | [08/09>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | SL [12>] (231) | [01/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | SL [12>] (231) | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | SLK [04>10] (171) | [02/07>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | SLK/SLC [11>] (172) | [12/12>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | SLK/SLC [11>] (172) | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | SLR [04>09] (199) Roadster | [>06/07] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | SLS [10>14] (197) Coupé | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | SLS [10>14] (197) Coupé | [01/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | SLS [11>14] (197) Roadster | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | SLS [11>14] (197) Roadster | [01/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Sprinter Classic (909) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Sprinter III (906) | [01/13>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Sprinter III (906) | [>10/11] | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Sprinter III (906) M.Y. 2013 | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | V / Viano [03>14] (639) | [08/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | V / Viano [03>14] (639) | [07/03>06/14] | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| V / Viano [03>14] (639) | [01/14>07/14] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 | |
| Viano (639) VAN | [01/14>07/14] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 | |
| Viano (639) VAN | [07/03>06/14] | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 | |
| Viano (639) VAN | [08/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 | |
| Vito (639) VAN | [03/14>] | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 | |
| Vito [03>14] (639) | [03/14>] | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 | |
| MINI | Mini (R55) [07>14] Clubman Cooper | [>09/09] | RSX | - | UVS02C4 | T-Pro 1 | - |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR* | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|------|-------|------|--------|------------|-------------|-------|-------------------|
| | | | | NEW | | NEW | NEW |

| | | | | | | | |
|--------------------------------------|---|----------|-----------|-----------|---------|---------|---|
| MINI | Mini (R55) [07>14] Clubman Cooper D | [>09/09] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Mini (R55) [07>14] Clubman Cooper S | [>09/09] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Mini (R55) [08>14] Clubman John Cooper Works | [08/09>] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R55) [08>14] Clubman John Cooper Works | [>09/09] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Mini (R55) [09>14] Clubman One | - | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R55) [10>14] Clubman One D | - | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R55) [11>14] Clubman Cooper SD | - | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R56) [06>13] Cooper | - | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R56) [06>13] Cooper S | - | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R56) [07>13] Cooper D | - | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R56) [07>13] One | - | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R56) [08>13] John Cooper Works | - | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R56) [09>13] One D | - | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R56) [11>13] Cooper SD | - | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R57) [09>15] Cabrio Cooper | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R57) [09>15] Cabrio Cooper | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R57) [09>15] Cabrio Cooper S | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R57) [09>15] Cabrio Cooper S | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R57) [09>15] Cabrio John Cooper Works | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R57) [09>15] Cabrio John Cooper Works | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R57) [09>15] Cabrio One | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R57) [09>15] Cabrio One | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R57) [10>15] Cabrio Cooper D | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R57) [10>15] Cabrio Cooper D | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R57) [11>15] Cabrio Cooper SD | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R57) [11>15] Cabrio Cooper SD | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R58) [11>15] Coupé Cooper | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R58) [11>15] Coupé Cooper | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R58) [11>15] Coupé Cooper S | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R58) [11>15] Coupé Cooper S | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R58) [11>15] Coupé Cooper SD | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R58) [11>15] Coupé Cooper SD | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R58) [11>15] Coupé John Cooper Works | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R58) [11>15] Coupé John Cooper Works | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R59) [12>15] Roadster Cooper | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R59) [12>15] Roadster Cooper | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R59) [12>15] Roadster Cooper S | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R59) [12>15] Roadster Cooper S | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R59) [12>15] Roadster Cooper SD | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R59) [12>15] Roadster Cooper SD | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R59) [12>15] Roadster John Cooper Works | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R59) [12>15] Roadster John Cooper Works | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| Mini (R60) [10>] Countryman Cooper | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - | |
| Mini (R60) [10>] Countryman Cooper | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - | |
| Mini (R60) [10>] Countryman Cooper D | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - | |
| Mini (R60) [10>] Countryman Cooper D | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - | |
| Mini (R60) [10>] Countryman Cooper S | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - | |
| Mini (R60) [10>] Countryman Cooper S | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - | |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|--------------------|---|----------|----------------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| MINI | Mini (R60) [10>] Countryman One | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R60) [10>] Countryman One | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R60) [10>] Countryman One D | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R60) [10>] Countryman One D | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R60) [11>] Countryman Cooper SD | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R60) [11>] Countryman Cooper SD | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R60) [13>] Countryman John Cooper Works | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R60) [13>] Countryman John Cooper Works | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R61) [13>] Paceman Cooper | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R61) [13>] Paceman Cooper | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R61) [13>] Paceman Cooper D | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R61) [13>] Paceman Cooper D | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R61) [13>] Paceman Cooper D | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R61) [13>] Paceman Cooper D | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R61) [13>] Paceman Cooper S | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R61) [13>] Paceman Cooper S | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R61) [13>] Paceman Cooper SD | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R61) [13>] Paceman Cooper SD | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (R61) [13>] Paceman John Cooper Works | [>05/14] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Mini (R61) [13>] Paceman John Cooper Works | [06/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mini (F55/F56) [14>] Cooper | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | Mini (F55/F56) [14>] Cooper D | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | Mini (F55/F56) [14>] Cooper S | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | Mini (F55/F56) [14>] Cooper SD | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | Mini (F55/F56) [14>] One | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| | Mini (F55/F56) [14>] One D | - | RSX | 1210-22X0 | UVS401X | T-Pro 2 | S3AX01 |
| MITSUBISHI | ASX [10>] (GA) | [06/14>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | i-MiEV [11>] (HA) | [06/14>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | L 200 [05>] (K) | [06/14>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Lancer [08>] (CY/CZ) Hatchback | [06/14>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Lancer [08>14] (CY/CZ) | [06/14>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Outlander [07>13] (CW) | [06/14>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Outlander [11>] (GA) Sport | [06/14>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Pajero [06>] (V80/V90) | [06/14>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| NISSAN | Pajero [08>] (KG/KH) Sport | [06/14>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 370Z [09>] (Z34) Coupé | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | 370Z [10>] (Z34) Cabriolet | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Cube [08>] (Z12) | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Evalia [12>] | - | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Frontier [98>] (D22) | [>12/04] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | GT-R [07>] | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Interstar | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Juke [10>] (F15) | - | - | - | UVS401X | T-Pro 2 | - |
| | Kubistar (X76) | - | RSX | - | - | T-Pro 2 | - |
| | Leaf [11>] | - | - | - | UVS401X | T-Pro 2 | - |
| | Micra [10>13] (K13) | - | - | - | - | T-Pro 2 | - |
| | Micra [13>] (K13) Facelift | - | - | - | - | T-Pro 2 | - |
| | Murano [08>] (Z51) | [>09/14] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Murano [08>] (Z51) | [10/14>] | - | - | UVS401X | T-Pro 2 | - |
| | Navara | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| Navara [05>] (D40) | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 | |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR* | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|------------------------------|----------------------------------|---------------|----------------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| NISSAN | Note [13>] (E12) | - | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | NV 200 | [04/14>] | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | NV 200 | [>03/14] | - | - | UVS401X | T-Pro 2 | - |
| | NV 400 | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Pathfinder [05>12] (R51) | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Pixo [09>] | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Primera [01>08] (P12E) Sedan | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Primera [01>08] (P12E) Wagon | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Primera [02>08] (P12E) Hatchback | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Qashqai [06>14] (J10) | [12/13>] | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Qashqai [08>14] +2 (J10) | [12/13>] | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Qashqai [14>] (J11) | - | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Teana [09>] (J32) | [01/14>] | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Tiida [04>] (C11) | [04/14>] | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Tiida [05>] (C11) Hatchback | [04/14>] | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Tiida [12>] | [04/14>] | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | X-Trail [07>13] (T31) | [04/13>] | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| X-Trail [14>] (T32) | [04/13>] | - | 1210-22X0 | UVS401X | T-Pro 2 | - | |
| OPEL (GM) | Adam [13>] | [>07/14] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Adam [13>] | [08/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Agila-B [08>] | [06/14>] | - | - | - | T-Pro 2 | - |
| | Ampera [12>] | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Antara [06>10] | [>11/10] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Antara [06>10] | [11/10>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Astra-H [04>10] | - | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Astra-H [04>10] Station Wagon | - | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Astra-H [04>10] Van | - | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Astra-H [05>10] Cabrio | - | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Astra-J [09>] | [>09/11] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Astra-J [09>] | [10/11>05/14] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Astra-J [09>] | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Astra-J [09>] Station Wagon | [10/11>05/14] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Astra-J [09>] Station Wagon | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Astra-J [09>] Station Wagon | [>09/11] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Astra-J [12>] Sedan | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Astra-J [12>] Sedan | [09/11>05/14] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Cascada [13>] | [>05/14] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Cascada [13>] | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Combo Tour [12>] | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Combo Van M.Y. 2012 | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Corsa-D [07>14] | [06/14>10/14] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Corsa-D [07>14] | [11/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Corsa-D [08>14] Van | [06/14>10/14] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Corsa-D [08>14] Van | [11/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Insignia [08>] Hatchback | [>09/11] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Insignia [08>] Hatchback | [09/11>04/14] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Insignia [08>] Hatchback | [04/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Insignia [08>] Sedan | [04/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Insignia [08>] Sedan | [09/11>04/14] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Insignia [08>] Sedan | [>09/11] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| Insignia [08>] Station Wagon | [04/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 | |
| Insignia [08>] Station Wagon | [09/11>04/14] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 | |
| Insignia [08>] Station Wagon | [>09/11] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 | |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR | INTELLESENS | T-PRO | ALCAR by SCHRADER |
|------------------|------------------------------------|---------------|----------------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| OPEL (GM) | Meriva-B [10>] | [08/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Mokka [12>] | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Movano B | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Signum [03>08] | - | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Vectra-C [01>08] | - | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Vectra-C [02>08] Station Wagon | - | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Vivaro-A | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Zafira-B [05>11] | [01/09>] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Zafira-B [05>11] | [>12/08] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | Zafira-C [12>] Tourer | [>05/14] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Zafira-C [12>] Tourer | [05/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| PEUGEOT | 1007 [05>10] (A08) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 107 [05>13] (B0) | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | 2008 [13>] (A9) | - | - | 1210-22X0 | - | T-Pro 2 | - |
| | 207 [06>12] (A7) Van | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 207 [06>12] (A7/T3) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 207 [07>12] (A7/T3) Station Wagon | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 207 [07>14] (A7) CC | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 207 [13>] Plus | - | - | - | - | - | - |
| | 208 [12>] (A9) | - | - | 1210-22X0 | - | T-Pro 2 | - |
| | 208 [12>] (Ai91) | - | - | 1210-22X0 | - | T-Pro 2 | - |
| | 3008 [09>] (T84) | [>09/13] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 3008 [09>] (T84) | [09/13>] | - | 1210-22X0 | - | T-Pro 2 | - |
| | 301 [12>] (M3) | - | - | - | - | - | - |
| | 307 [00>05] (T5) | [11/03>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 307 [00>05] (T5) Station Wagon | [11/03>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 307 [01>05] (T5) CC | [11/03>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 307 [05>09] (T6) | [01/07>12/07] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 307 [05>09] (T6) | [>12/06] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 307 [05>09] (T6) CC | [01/07>12/07] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 307 [05>09] (T6) CC | [>12/06] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 307 [05>09] (T6) Station Wagon | [>12/06] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 307 [05>09] (T6) Station Wagon | [01/07>12/07] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 308 [07>13] (T7) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 308 [08>13] (T7) Station Wagon | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 308 [08>13] (T7) Station Wagon Van | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 308 [09>13] (T7) CC | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 308 [13>] (T9) | - | - | - | - | - | - |
| | 4008 [12>] (J3) | [06/14>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 407 [04>11] (D2) | [>02/06] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 407 [04>11] (D2) Break | [>02/06] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 407 [04>11] (D2) Break Van | [>02/06] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 407 [05>11] (D2) Coupé | [>02/06] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 408 [10>] (T7) | [06/14>] | - | 1210-22X0 | - | T-Pro 2 | - |
| | 5008 [09>] (T8) | [>09/13] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 5008 [09>] (T8) | [09/13>] | - | 1210-22X0 | - | T-Pro 2 | - |
| | 508 [11>] (W2) | [>09/13] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 508 [11>] (W2) | [09/13>] | - | 1210-22X0 | - | T-Pro 2 | - |
| | 508 [11>] (W2) Break | [09/13>] | - | 1210-22X0 | - | T-Pro 2 | - |
| | 508 [11>] (W2) Break | [>09/13] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 607 [00>04] (Z8) | - | - | 1210-22X0-2020 | - | - | S3AX01 |
| 607 [04>10] (Z9) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 | |
| 807 [02>] (V2) | [>10/05] | - | 1210-22X0-2020 | - | - | S3AX01 | |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR* | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|------|-------|------|--------|------------|-------------|-------|-------------------|
| | | | | NEW | | NEW | NEW |

| | | | | | | | |
|-------------------------------------|---|---------------|-----|----------------|---------|---------|--------|
| PEUGEOT | 807 [02>] (V2) | [10/05>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 807 [06>] (V2) Van | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Bipper | [06/14>] | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Bipper Tepee [08>] (A9) | [06/14>] | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Boxer (U9) | [01/14>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Boxer (U9) | [>11/13] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Expert (G9) | [09/06>12/13] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Expert (G9) | [06/14>] | - | 1210-22X0 | - | - | - |
| | iOn [11>] | [06/14>] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Partner (B9) | [>06/14] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Partner (B9) | [07/14>] | - | 1210-22X0 | - | T-Pro 2 | - |
| | Partner Tepee [08>] (B9) | [07/14>] | - | 1210-22X0 | - | T-Pro 2 | - |
| | Partner Tepee [08>] (B9) | [>06/14] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | RCZ [10>] (T75) | [>09/13] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | RCZ [10>] (T75) | [10/13>] | - | 1210-22X0 | - | T-Pro 2 | - |
| PORSCHE | 911 [05>08] (997) Cabriolet | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 911 [05>11] (997) | [>06/08] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 911 [05>11] (997) | [07/08>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 911 [05>11] (997) Carrera 4 | [>06/08] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 911 [05>11] (997) Carrera 4 | [07/08>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 911 [05>11] (997) Carrera 4 Cabriolet | [>06/08] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 911 [05>11] (997) Carrera 4 Cabriolet | [07/08>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 911 [05>11] (997) Carrera 4 S | [>06/08] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 911 [05>11] (997) Carrera 4 S | [07/08>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 911 [05>11] (997) Carrera 4 S Cabriolet | [>06/08] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 911 [05>11] (997) Carrera 4 S Cabriolet | [07/08>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 911 [05>11] (997) Carrera S | [>06/08] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 911 [05>11] (997) Carrera S | [07/08>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 911 [05>11] (997) Carrera S Cabriolet | [>06/08] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 911 [05>11] (997) Carrera S Cabriolet | [07/08>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 911 [05>11] (997) Targa 4 | [>06/08] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 911 [05>11] (997) Targa 4 | [07/08>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 911 [05>11] (997) Targa 4S | [07/08>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 911 [05>11] (997) Targa 4S | [>06/08] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 911 [06>09] (997) Carrera Turbo Cabriolet 4x4 | [07/08>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 911 [06>09] (997) Carrera Turbo Cabriolet 4x4 | [>06/08] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 911 [06>11] (997) GT3 | [07/08>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 911 [06>11] (997) GT3 | [>06/08] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 911 [07>09] (997) GT2 | [07/08>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 911 [07>09] (997) GT2 | [>06/08] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | 911 [10>11] (997) GT2 RS | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 911 [12>] (991) Carrera | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 911 [12>] (991) Carrera 4 | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 911 [12>] (991) Carrera 4S | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 911 [12>] (991) Carrera 4S Cabriolet | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| 911 [12>] (991) Carrera Cabriolet | - | RSX | - | UVS02C4 | T-Pro 1 | - | |
| 911 [12>] (991) Carrera Cabriolet 4 | - | RSX | - | UVS02C4 | T-Pro 1 | - | |
| 911 [12>] (991) Carrera S | - | RSX | - | UVS02C4 | T-Pro 1 | - | |
| 911 [12>] (991) Carrera S Cabriolet | - | RSX | - | UVS02C4 | T-Pro 1 | - | |
| 911 [12>] (991) Targa 4 | - | RSX | - | UVS02C4 | T-Pro 1 | - | |
| 911 [12>] (991) Targa 4S | - | RSX | - | UVS02C4 | T-Pro 1 | - | |
| 911 [12>] (991) Turbo | - | RSX | - | UVS02C4 | T-Pro 1 | - | |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.
*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0
Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.
*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

This document is strictly confidential. All copying, in part or in whole, is strictly forbidden without the prior authorisation of TEXA S.p.A. Future specifications, descriptions and appearances may vary with respect to this brochure. TEXA S.p.A. reserves the right to modify its products without prior notice.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|----------------------------------|-----------------------------------|----------|----------------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| PORSCHE | 911 [12>] (991) Turbo Cabriolet | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 911 [13>] (991) GT3 | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 911 [13>] (991) Turbo S | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | 911 [13>] (991) Turbo S Cabriolet | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Boxster [04>11] (987) | [>06/08] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Boxster [04>11] (987) | [07/08>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Boxster [08>11] (987) Spyder | [07/08>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Boxster [12>] (981) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Boxster [12>] (981) S | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Boxster [13>] (981) GTS | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Cayenne [02>07] (9PA/955) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Cayenne [02>07] (9PA/955) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Cayenne [07>10] (9PA/957) | [>04/14] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Cayenne [07>10] (9PA/957) | [05/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Cayenne [07>10] (9PA/957) | [>04/14] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Cayenne [07>10] (9PA/957) | [05/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Cayenne [10>] (92A/958) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Cayenne [10>] (92A/958) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Cayman [05>12] (987C) S | [01/09>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Cayman [05>12] (987C) S | [>12/08] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Cayman [06>12] (987C) | [>12/08] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Cayman [06>12] (987C) | [01/09>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Cayman [13>] (981) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Cayman [13>] (981) S | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Cayman [14>] (981) GTS | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Macan [14>] (95B) S | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Macan [14>] (95B) S Diesel | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Macan [14>] (95B) Turbo | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Panamera [09>] (970) | [01/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Panamera [09>] (970) | [>12/13] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Panamera [09>] (970) 4 | [01/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Panamera [09>] (970) 4 | [>12/13] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Panamera [09>] (970) 4 S | [01/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Panamera [09>] (970) 4 S | [>12/13] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Panamera [09>] (970) S | [>12/13] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Panamera [09>] (970) S | [01/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Panamera [09>] (970) Turbo | [>12/13] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Panamera [09>] (970) Turbo | [01/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Panamera [11>] (970) Diesel | [01/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Panamera [11>] (970) Diesel | [>12/13] | RSX | - | UVS02C4 | T-Pro 1 | - |
| Panamera [11>] (970) GTS | [01/14>] | RSX | 1210-22X0 | UVS09X4 | - | - | |
| Panamera [11>] (970) GTS | [>12/13] | RSX | - | UVS02C4 | T-Pro 1 | - | |
| Panamera [11>] (970) S Hybrid | [01/14>] | RSX | 1210-22X0 | UVS09X4 | - | - | |
| Panamera [11>] (970) S Hybrid | [>12/13] | RSX | - | UVS02C4 | T-Pro 1 | - | |
| Panamera [11>] (970) Turbo S | [01/14>] | RSX | 1210-22X0 | UVS09X4 | - | - | |
| Panamera [11>] (970) Turbo S | [>12/13] | RSX | - | UVS02C4 | T-Pro 1 | - | |
| RENAULT | Captur [13>] (X87/J5) | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Clio II [01>11] Facelift | - | - | - | - | - | - |
| | Clio II [01>11] Facelift Van | - | - | - | - | - | - |
| | Clio III [05>12] (BR) | - | - | - | - | - | - |
| | Clio III [07>12] (KR) Grandtour | - | - | - | - | - | - |
| | Clio IV [12>] (X98/BH) | [06/14>] | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| Clio IV [13>] (X98/KH) Grandtour | [06/14>] | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 | |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR* | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|------------------------|-------------------------------------|----------|----------------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| RENAULT | Espace IV [02>14] (JK) | [>06/14] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Espace IV [02>14] (JK) | [06/14>] | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Fluence [09>] (X38/L3) | [>06/15] | RSX | 1210-22X0-2020 | - | - | S3AX01 |
| | Fluence [09>] (X38/L3) | [07/15>] | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Fluence ZE [13>] (X38/L3) | [>06/15] | RSX | 1210-22X0-2020 | - | - | S3AX01 |
| | Fluence ZE [13>] (X38/L3) | [07/15>] | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Grand Espace IV [02>14] (JK) | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Kangoo II [08>] (X61/FW) | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Kangoo ZE [11>] (X61/FW) | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Koleos [08>] (HY) | [>12/13] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Koleos [08>] (HY) | [01/14>] | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Laguna II [01>07] (BG) | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Laguna II [01>07] (KG) Grandtour | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Laguna III [07>] (X91/BT) | - | RSX | 1210-22X0-2020 | - | - | S3AX01 |
| | Laguna III [07>] (X91/KT) Grandtour | - | RSX | 1210-22X0-2020 | - | - | S3AX01 |
| | Laguna III [08>] (X91/DT) Coupé | - | RSX | 1210-22X0-2020 | - | - | S3AX01 |
| | Master 3 | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Megane I [96>03] (X64) | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Megane II [02>09] (BM) | - | RSX | 1210-22X0-2020 | - | - | S3AX01 |
| | Megane II [03>09] (KM) Grandtour | - | RSX | 1210-22X0-2020 | - | - | S3AX01 |
| | Megane II [03>09] (LM) Limousine | - | RSX | 1210-22X0-2020 | - | - | S3AX01 |
| | Megane II [03>10] (EM) C-C | - | RSX | 1210-22X0-2020 | - | - | S3AX01 |
| | Megane III [09>] (X95/BZ) | [>06/15] | RSX | 1210-22X0-2020 | - | - | S3AX01 |
| | Megane III [09>] (X95/BZ) | [07/15>] | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Megane III [09>] (X95/DZ) Coupé | [07/15>] | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Megane III [09>] (X95/DZ) Coupé | [>06/15] | RSX | 1210-22X0-2020 | - | - | S3AX01 |
| | Megane III [09>] (X95/KZ) Grandtour | [>06/15] | RSX | 1210-22X0-2020 | - | - | S3AX01 |
| | Megane III [09>] (X95/KZ) Grandtour | [07/15>] | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Megane III [10>] (X95/EZ) C-C | [>06/15] | RSX | 1210-22X0-2020 | - | - | S3AX01 |
| | Megane III [10>] (X95/EZ) C-C | [07/15>] | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Modus [04>] (FP/JP) | - | - | - | - | - | - |
| | Scenic I [95>03] (JA) | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Scenic II [03>09] (JM) | [>10/07] | RSX | 1210-22X0-2020 | - | - | S3AX01 |
| | Scenic III [09>] (X95/JZ) | [>06/15] | RSX | 1210-22X0-2020 | - | - | S3AX01 |
| | Scenic III [09>] (X95/JZ) | [07/15>] | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Scenic III [09>] (X95/JZ) X-Mod | [>06/15] | RSX | 1210-22X0-2020 | - | - | S3AX01 |
| | Scenic III [09>] (X95/JZ) X-Mod | [07/15>] | - | 1210-22X0 | UVS401X | T-Pro 2 | - |
| | Symbol [09>] (LU) | [04/13>] | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Twingo II [07>14] (CN/GN) | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Twingo III [14>] (X07/BC) | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| Vel Satis [02>09] (BJ) | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 | |
| Wind [10>] (E4) | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 | |
| Zoe [13>] (X10) | - | RSX | 1210-22X0-2020 | - | - | S3AX01 | |
| SAAB | 9-3 [02>11] (9440) | - | RSX | - | UVS09X4 | T-Pro 1 | - |
| | 9-3 [03>11] (9440) Cabrio | - | RSX | - | UVS09X4 | T-Pro 1 | - |
| | 9-3 [05>11] (9440) Wagon | - | RSX | - | UVS09X4 | T-Pro 1 | - |
| | 9-3 X [09>11] (9440) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | 9-5 [97>10] (9600) | [11/06>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | 9-5 [97>10] (9600) | [>10/06] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | 9-5 [98>10] (9600) Wagon | [>10/06] | RSX | - | UVS09X4 | T-Pro 1 | - |
| | 9-5 [98>10] (9600) Wagon | [11/06>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| SEAT | Alhambra [10>] (710) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Altea [04>] (5P1) | - | RSX | 1210-22X0 | UVS09X4 | - | - |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|--------------------------|----------------------------------|----------|----------------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| SEAT | Altea Freetrack [07>] (5P8) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Altea XL [06>] (5P5) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Exeo [09>13] (3R2) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Exeo [09>13] (3R5) Station Wagon | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Ibiza [08>15] (6J1) Sportcoupé | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Ibiza [08>15] (6J5) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Ibiza [10>15] (6J8) ST | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Leon [12>] (5F1) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Leon [12>] (5F5) SC | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Leon [14>] (5F8) ST | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Mii [12>] (KF1) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| Toledo [12>] (KG3) | - | RSX | 1210-22X0 | UVS09X4 | - | - | |
| SKODA | Citigo [12>] (NF1) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Fabia [07>14] (5J2/582) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Fabia [07>14] (5J5) Kombi | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Octavia [05>10] (1U5) Kombi Tour | [02/04>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Octavia [96>10] (1U2) | [02/04>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Octavia [96>10] (1U5) Kombi | [02/04>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Octavia [04>13] (1Z3) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Octavia [04>13] (1Z5) Kombi | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Octavia [13>] (5E3) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Octavia [13>] (5E5) Kombi | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Roomster [06>] (5J7) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Superb [09>15] (374) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Superb B6 [08>15] (3T4) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Superb B6 [09>15] (3T5) Kombi | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| Yeti [09>] (5L7) | - | RSX | 1210-22X0 | UVS09X4 | - | - | |
| SMART | Forfour [14>] (453) | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Fortwo [07>14] (451) Cabrio | [12/12>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Fortwo [07>14] (451) Cabrio | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Fortwo [07>14] (451) Coupé | [12/12>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Fortwo [07>14] (451) Coupé | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Fortwo [12>] (451) EV Cabrio | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Fortwo [12>] (451) EV Cabrio | [12/12>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Fortwo [12>] (451) EV Coupé | [12/12>] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Fortwo [12>] (451) EV Coupé | [>12/12] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| Fortwo [14>] (453) Coupé | - | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 | |
| SSANGYONG | Actyon [05>] (C100) | [11/14>] | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Actyon [12>] Sports II (Q150) | [11/14>] | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Korando [11>] (C200) | [08/13>] | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Korando [12>] Sports (Q150) | [08/13>] | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Korando [13>] Turismo (A150) | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Rexton III (W) [13>] (Y290) | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| Rodius [13>] (A149) | - | - | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 | |
| SUBARU | BRZ [12>] (Z10) | [01/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Forester [12>] (SJ) | [01/14>] | RSX | - | - | T-Pro 2 | - |
| | Impreza [11>] (GJ) | [01/14>] | RSX | - | - | T-Pro 2 | - |
| | Impreza [11>] (GP) Hatchback | [01/14>] | RSX | - | - | T-Pro 2 | - |
| | Legacy [09>14] (BM) | [10/14>] | RSX | - | - | T-Pro 2 | - |
| | Legacy [09>14] (BR) Kombi | [10/14>] | RSX | - | - | T-Pro 2 | - |
| | Outback [09>14] (BR) | [01/14>] | RSX | - | - | T-Pro 2 | - |
| | Trezia [11>] (NS/NL) | [01/14>] | RSX | - | - | T-Pro 2 | - |
| Tribeca [05>] (B9) | [01/14>] | RSX | - | - | T-Pro 2 | - | |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR* | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|---------------------|---------------------------------|---------------|----------------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| SUBARU | XV Crosstrek [12>] (GP) | [01/14>] | RSX | - | - | T-Pro 2 | - |
| SUZUKI | Alto [08>] (GF) | [06/14>] | - | - | - | T-Pro 2 | - |
| | Jimny [98>] (FJ) | [06/14>] | - | - | - | T-Pro 2 | - |
| | Splash [08>] (EX) | [06/14>] | - | - | - | T-Pro 2 | - |
| | Swift [10>] (AZ) | [06/14>] | - | - | - | T-Pro 2 | - |
| | Sx4 [06>] (EY/GY) | [06/14>] | - | - | - | T-Pro 2 | - |
| | Sx4 [13>] (JY) S-Cross | [06/14>] | - | - | - | T-Pro 2 | - |
| TOYOTA | Alphard II [08>] (H20) | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Auris [13>] (E18) | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Auris [13>] (E18) Wagon | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Avenis [03>08] (T25) Liftback | [01/05>12/05] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Avenis [03>08] (T25) Sedan | [01/05>12/05] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Avenis [03>08] (T25) Wagon | [01/05>12/05] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Avenis [08>] (T27) | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Avenis [08>] (T27) Wagon | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Aygo [14>] (B40) | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Camry [12>] (V5) | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Camry [12>] (V5) Hybrid | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Corolla [06>13] (E14) Altis | [09/13>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Corolla [08>] (E13) | [09/13>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Corolla [11>] (E14) Altis | [09/13>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Corolla [12>] (E16) Axio | [09/13>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Corolla [13>] (E18) | [09/13>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | FJ Cruiser [07>] (J15) | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | GT86 [13>] (N6) | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | iQ [08>] (J10) | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | iQ [13>] (J10) EV | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Land Cruiser [07>] (J20) | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Land Cruiser [09>] (J15) Prado | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Prius [09>] (ZVW) | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Prius [10>] (ZVW) Plug-in | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | RAV4 [05>12] (A3) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | RAV4 [13>] (A4) | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Tacoma [04>15] (N2) | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Tundra II [07>] (K5) | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Urban Cruiser [09>14] (P11) | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | Verso [09>] (R2) | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| Verso-S [11>] (P12) | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 | |
| Yaris [11>] (P13) | [06/14>] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 | |
| VOLKSWAGEN | Amarok [10>] (2H) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Beetle (Maggiolino) [11>] (5C1) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Caddy (2C-2K) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Caddy (2K) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Caddy [03>07] (170-174) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Caddy [04>10] (2K) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Caddy [10>] (2C/2K) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Caravelle (T5) (7E) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Caravelle (T5) (7H) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Crafter | [04/06>] | RSX | 1210-22X0-2020 | - | T-Pro 2 | S3AX01 |
| | Eos [06>10] (1F7) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Eos [11>] (1F8) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Golf VI [08>13] (5K1) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Golf VI [09>13] (AJ5) Variant | - | RSX | 1210-22X0 | UVS09X4 | - | - |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|--------------------------|---------------------------------|---------------|-----------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| VOLKSWAGEN | Golf VI [09>14] (521) Plus | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Golf VI [11>] (517) Cabriolet | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Golf VII [12>] (5G1) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Golf VII [14>] (BA5) Variant | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Golf VII [14>] (BE1) EV | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Jetta [10>] (162) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | New Beetle [97>10] (1C1) | - | RSX | - | - | - | - |
| | New Beetle [98>10] (9C1) | - | RSX | - | - | - | - |
| | New Beetle [03>10] (1Y7) Cabrio | - | RSX | - | - | - | - |
| | Passat B6 [04>10] (3C2) | - | RSX | - | - | - | - |
| | Passat B6 [05>10] (3C5) Variant | - | RSX | - | - | - | - |
| | Passat B7 [10>14] (362) | [>09/13] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Passat B7 [10>14] (362) | [09/13>12/14] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Passat B7 [10>14] (365) Variant | [>09/13] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Passat B7 [10>14] (365) Variant | [09/13>12/14] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Passat B7 [12>] NMS (A32) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Passat CC [08>12] (357) | [>09/14] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Passat CC [08>12] (357) | [10/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Passat CC [12>] (358) | [>09/14] | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Passat CC [12>] (358) | [10/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Phaeton [02>06] (3D8) L | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Phaeton [02>10] (3D2) | [>06/07] | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Phaeton [02>10] (3D2) | [06/07>] | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Polo [09>14] (6R1) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Polo [14>] (6C1) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Scirocco [08>14] (137) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Scirocco [14>] (138) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Sharan [10>] (7N1) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Tiguan [07>12] (5N1) | - | RSX | 1210-22X0-2020 | UVS09X4 | T-Pro 1 | S3AX01 |
| | Tiguan [12>] (5N2) | - | RSX | 1210-22X0 | UVS09X4 | - | - |
| | Touareg [02>06] (7LA) | - | RSX | 1210-22X0-2020 | - | T-Pro 1 | S3AX01 |
| | Touareg [06>10] (7L6) | - | RSX | - | UVS02C4 | T-Pro 1 | - |
| | Touareg [10>] (7P5) | [03/14>] | RSX | 1210-22X0 | UVS09X4 | - | - |
| Touareg [10>] (7P5) | [>02/14] | RSX | - | UVS02C4 | T-Pro 1 | - | |
| Touran [10>15] (1T3) | - | RSX | 1210-22X0 | UVS09X4 | - | - | |
| Transporter (T5) (7E-7F) | - | RSX | 1210-22X0 | UVS09X4 | - | - | |
| Transporter (T5) (7H-7J) | - | RSX | 1210-22X0 | UVS09X4 | - | - | |
| Up! [11>] (121) | - | RSX | 1210-22X0 | UVS09X4 | - | - | |
| Up! [14>] (6A1) | - | RSX | 1210-22X0 | UVS09X4 | - | - | |
| VOLVO | C30 [06>13] | - | RSX | - | UVS401X | T-Pro 2 | - |
| | S60 I [00>09] | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | S60 II [10>] | [07/14>] | - | - | - | - | - |
| | S80 II [06>] | [02/14>] | - | - | - | - | - |
| | S80 II L [09>] | [02/14>] | - | - | - | - | - |
| | V40 [12>] | [07/14>] | - | - | - | - | - |
| | V40 [12>] Cross Country | [07/14>] | - | - | - | - | - |
| | V50 [04>12] | - | RSX | - | UVS401X | T-Pro 2 | - |
| | V60 [10>] | [07/14>] | - | - | - | - | - |
| | V60 [10>] | [>06/14] | RSX | - | UVS401X | T-Pro 2 | - |
| | V60 [13>] Plug-In Hybrid | [>06/14] | RSX | - | UVS401X | T-Pro 2 | - |
| | V60 [13>] Plug-In Hybrid | [07/14>] | - | - | - | - | - |
| | V70 II [00>07] | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| V70 III [07>] | [>06/14] | RSX | - | UVS401X | T-Pro 1 | - | |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.
*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0
Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.
*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

This document is strictly confidential. All copying, in part or in whole, is strictly forbidden without the prior authorisation of TEXA S.p.A. Future specifications, descriptions and appearances may vary with respect to this brochure. TEXA S.p.A. reserves the right to modify its products without prior notice.

| MAKE | MODEL | YEAR | SENSIT | EZ-SENSOR* | INTELLISENS | T-PRO | ALCAR by SCHRADER |
|-------|----------------|----------|--------|----------------|-------------|---------|-------------------|
| | | | | NEW | | NEW | NEW |
| VOLVO | V70 III [07>] | [07/14>] | - | - | - | - | - |
| | XC60 [09>] | [>06/14] | RSX | - | UVS401X | T-Pro 2 | - |
| | XC60 [09>] | [07/14>] | - | - | - | - | - |
| | XC70 II [07>] | [>10/08] | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |
| | XC70 II [07>] | [>06/14] | RSX | - | UVS401X | T-Pro 2 | - |
| | XC70 II [07>] | [07/14>] | - | - | - | - | - |
| | XC90 I [03>14] | - | RSX | 1210-22X0-2020 | UVS401X | T-Pro 1 | S3AX01 |

Nota: tutti gli strumenti TPMS TEXA sono compatibili alla lettura dei sensori marchiati VDO REDi-Sensor™.

*EZ SENSOR: il codice ricambio 2020 si riferisce al sensore EZ-sensor; i codici ricambio 1210 e 22x0 si riferiscono al sensore EZ-sensor 2.0

Note: all TEXA's TPMS tools are compatible with the reading of the VDO REDi-Sensor™ branded sensors.

*EZ SENSOR: the spare part code 2020 refers to the EZ-sensor; the spare part codes 1210 and 22x0 refer to the EZ-sensor 2.0.

This document is strictly confidential. All copying, in part or in whole, is strictly forbidden without the prior authorisation of TEXA S.p.A. Future specifications, descriptions and appearances may vary with respect to this brochure. TEXA S.p.A. reserves the right to modify its products without prior notice.

This document is strictly confidential. All copying, in part or in whole, is strictly forbidden without the prior authorisation of TEXA S.p.A. Future specifications, descriptions and appearances may vary with respect to this brochure. TEXA S.p.A. reserves the right to modify its products without prior notice.

WARNING

The trademarks and logos of vehicle manufacturers in this document have been used exclusively for information purposes and are used to clarify the compatibility of TEXA products with the models of vehicles identified by the trademarks and logos. Because TEXA products and software are subject to continuous developments and updates, upon reading this document they may not be able to carry out the DIAGNOSTICS of all the models and electronic systems of each vehicle manufacturer mentioned within this document. References to the makes, models and electronic systems within this document must therefore be considered purely indicative and TEXA recommends to always check the list of the "Systems that can be diagnosed" of the product and/or software at TEXA authorized retailers before any purchase. **The images and the vehicle outlines within this document have been included for the sole purpose of making it easier to identify the vehicle category (car, truck, motorbike, etc.) for which the TEXA product and/or software is intended.** The data, descriptions and illustrations may change compared to those described in this document. TEXA S.p.A. reserves the right to make changes to its products without prior notice.



+39 0422 791311



www.texa.com



info.it@texa.com



www.facebook.com/texacom



www.twitter.com/texacom



www.youtube.com/texacom



**COMPANY WITH
QUALITY SYSTEM
CERTIFIED BY DNV
= ISO 9001 =**

The BLUETOOTH brand is the property of Bluetooth SIG, Inc., U.S.A., and is used by TEXA S.p.A. under license.

Copyright TEXA S.p.A. - 10/2015

MADE IN ITALY

